

Technical Service Bulletin

Date: January 27, 2011

Service Bulletin-No.: 2011012701
Description: Recall Notice
Product: 85084
Production Codes: 06448-1.02, 06449-1.02, 06540-1.02, 16041-1.02

Recall: part number 85084, MCS 5-115/24 power supply.

The 85084 is specified as an 110V AC input; however, the affected units are internally set to a 230V AC input, and will not operate at 110V AC. Affected units were shipped between December 6, 2010 and January 25, 2011, with production codes of 06448-1.02, 06449-1.02, 06540-1.02, and 16041-1.02.

Your Murrelektronik Inside Sales Associate will issue an RMA for any affected units you have received, and replacements or credit will be issued.

<u>Contact Information:</u>	<u>Customer Service</u>	<u>770-497-9292</u>	
	Teresa Whitley	ext. 201	twhitley@murrinc.com
	Tamara DeCosta	ext. 206	tdecosta@murrinc.com
	Carmen Burt	ext. 203	cburt@murrinc.com
	<u>Technical Support</u>	<u>770-497-9292</u>	
	Bart Caudell	ext. 202	bcaudell@murrinc.com

Thank you for your cooperation and patience in this matter.

With Best Regards,

Murrelektronik, Inc.